

Log sheet Completed By: A.Thompson / S. Tracski
Log sheet Completion date: 2015-07-06 JDAY:182

Ignore columns that are not applicable to your program
* If preferred, use decimal degrees with five or six decimal places
* (NS (+/-) (EW) (+/-)

Line #	Seq #	Date	Time (UTC)	Latitude* whole degrees	Latitude* decimal minutes	Longitude* whole degrees	Longitude* decimal minutes	Date	Time (UTC)	Latitude* whole degrees	Latitude* decimal minutes	Longitude* whole degrees	Longitude* decimal minutes	Start		End		3590 tape #s	Sample Rate ms	Sample Length seconds	# Channels	Contact person	Comments
														shot #	file #	shot #	file #						
MGL15102860	001	2015-06-02	20:39	39	35.39087	-73	24.99570	2015-06-03	02:48	39	42.68160	-73	39.36727	950	1	5161	4299	1-2	0.5	4.096	240	Thompson	Syntrak recording files have incorrect numbering at SOL
MGL15101924	002	2015-06-03	03:56	39	39.77995	-73	40.15537	2015-06-03	10:16	39	23.31262	-73	10.15398	5089	1	864	4123	3-5	0.5	4.096	240	Thompson	
MGL15102836	003	2015-06-03	19:34	39	28.5606	-73	37.98417	2015-06-04	01:48	39	37.83977	-73	29.69117	876	1	5137	4262	6-7	0.5	4.096	240	Thompson	
MGL15101990	004	2015-06-04	02:58	39	39.82540	-73	40.41962	2015-06-04	04:51	39	35.47250	-73	32.25262	5108	1	8628	1277	8	0.5	4.096	240	Thompson	Line terminated d/t failure of P-cable GPS
MGL15102812	005	2015-06-04	17:40	39	28.67405	-73	37.92997	2015-06-04	23:58	39	42.46685	-73	39.39586	851	1	5137	4267	9-10	0.5	4.096	240	Thompson	
MGL15101908R	006	2015-06-05	01:07	39	39.83727	-73	40.42427	2015-06-05	07:29	39	23.12156	-73	10.15307	5110	1	865	4246	11-12	0.5	4.096	240	Thompson	
MGL15102788	007	2015-06-05	08:38	39	28.11948	-73	38.56898	2015-06-05	14:53	39	42.39425	-73	38.37308	872	1	5137	4266	13-14	0.5	4.096	240	Tracski	
MGL15101876	008	2015-06-05	16:03	39	39.77405	-73	40.47128	2015-06-05	22:28	39	23.15722	-73	10.29700	5109	1	865	4245	15-16	0.5	4.096	240	Thompson	
MGL15102764	009	2015-06-05	23:36	39	25.67688	-73	38.17667	2015-06-06	03:11	39	35.22843	-73	35.22843	884	1	3812	2429	17	0.5	4.096	240	Thompson	
MGL15101852	010	2015-06-06	14:20	39	23.09493	-73	10.35425	2015-06-06	20:35	39	23.09493	-73	10.35425	5000	120	4255	865	18-19	0.5	4.096	240	Thompson	Files 1-119 intermittent SP's d/t issue with Spectra
MGL15102740	011	2015-06-06	21:43	39	25.61658	-73	38.24305	2015-06-07	03:56	39	31.69300	-73	19.20522	885	1	5137	4249	20-21	0.5	4.096	240	Thompson	
MGL15101828	012	2015-06-07	05:04	39	39.71663	-73	40.72720	2015-06-07	11:26	39	23.04235	-73	10.40307	5125	1	865	4261	22-23	0.5	4.096	240	Thompson	
MGL15102716	013	2015-06-07	13:07	39	25.42658	-73	38.09497	2015-06-07	19:40	39	25.42658	-73	38.55390	857	1	5137	4225	24-25	0.5	4.096	240	Thompson	
MGL15101924R	014	2015-06-07	20:44	39	39.91097	-73	40.35683	2015-06-08	03:30	39	23.29628	-73	10.16857	5110	1	865	4246	26-27	0.5	4.096	240	Thompson	
MGL15102692	015	2015-06-08	04:31	39	25.40552	-73	38.23460	2015-06-08	08:09	39	24.36668	-73	24.43887	856	1	2986	2121	28	0.5	4.096	240	Thompson	Line terminated d/t failure of P-cable system
MGL15102688	016	2015-06-08	20:37	39	26.36406	-73	38.36996	2015-06-09	03:01	39	42.05633	-73	38.67983	876	1	5137	4262	29-30	0.5	4.096	240	Thompson	
MGL15101804	017	2015-06-09	04:10	39	39.26628	-73	40.07903	2015-06-09	10:45	39	22.97433	-73	10.46517	5028	1	865	4162	31-32	0.5	4.096	240	Tracski	
MGL15102644	018	2015-06-09	11:48	39	28.36818	-73	38.51486	2015-06-09	18:12	39	42.00188	-73	38.73222	890	1	5137	4247	33-34	0.5	4.096	240	Thompson	
MGL15101780	019	2015-06-09	20:17	39	37.24338	-73	36.57763	2015-06-10	01:34	39	23.29193	-73	11.18965	4529	1	960	3570	35-36	0.5	4.096	240	Thompson	
MGL15102620	020	2015-06-10	01:34	39	25.26112	-73	38.49998	2015-06-10	09:24	39	41.93203	-73	38.79633	878	1	5137	4260	37-38	0.5	4.096	240	Tracski	
MGL15101780R	021	2015-06-10	10:30	39	39.51528	-73	40.72022	2015-06-10	17:13	39	22.89808	-73	10.53822	5106	1	865	4242	39-40	0.5	4.096	240	Thompson	
MGL15102596	022	2015-06-10	18:21	39	26.20552	-73	38.55917	2015-06-11	01:06	39	41.86847	-73	39.83326	879	1	5137	4253	41-42	0.5	4.096	240	Thompson	
MGL15101756	023	2015-06-11	02:12	39	39.51305	-73	40.92403	2015-06-11	09:01	39	22.84102	-73	10.58822	5129	1	865	4264	43-44	0.5	4.096	240	Thompson	
MGL15102688R	024	2015-06-11	14:51	39	27.84193	-73	12.71665	2015-06-11	20:14	39	42.34213	-73	38.42082	1503	1	5137	3635	45-46	0.5	4.096	240	Thompson	
MGL15101732	025	2015-06-11	21:30	39	39.46977	-73	40.92080	2015-06-12	03:45	39	22.77538	-73	10.64860	5125	1	865	4261	47-48	0.5	4.096	240	Thompson	
MGL1510260R	026	2015-06-12	05:48	39	25.82253	-73	37.72087	2015-06-12	12:17	39	42.59383	-73	38.19038	854	1	5137	4284	49-50	0.5	4.096	240	Thompson	
MGL15101708	027	2015-06-12	13:42	39	39.43985	-73	41.18348	2015-06-12	20:18	39	22.70547	-73	10.71293	5147	1	865	4283	51-52	0.5	4.096	240	Thompson	
MGL15102572	028	2015-06-12	21:25	39	26.12813	-73	38.98688	2015-06-13	04:08	39	41.82688	-73	39.82270	875	1	5137	4263	53-54	0.5	4.096	240	Thompson	
MGL15101852I	029	2015-06-13	05:09	39	40.06318	-73	40.47580	2015-06-13	10:17	39	27.98642	-73	17.98243	5129	1	3186	1944	55-56	0.5	4.096	240	Thompson	
MGL15102692R	030	2015-06-13	11:22	39	29.52720	-73	16.63940	2015-06-13	16:35	39	42.14573	-73	38.60087	1913	1	5136	3225	57-58	0.5	4.096	240	Thompson	
MGL15101684	031	2015-06-13	17:48	39	39.30950	-73	38.60087	2015-06-14	00:19	39	22.63400	-73	10.77915	5125	1	865	4261	59-60	0.5	4.096	240	Thompson	
MGL15102548	032	2015-06-14	01:26	39	25.09018	-73	38.72867	2015-06-14	07:47	39	41.73770	-73	38.87410	885	1	5137	4253	61-62	0.5	4.096	240	Thompson	1690-EOL DNP d/t large number of power down
MGL15101660	033	2015-06-14	08:54	39	39.31365	-73	41.28788	2015-06-14	15:18	39	22.74957	-73	11.16358	5145	1	911	4235	63-64	0.5	4.096	240	Thompson	
MGL15102572R	034	2015-06-14	16:45	39	25.44602	-73	39.21457	2015-06-14	22:52	39	42.12832	-73	38.61670	961	1	5137	4176	65-66	0.5	4.096	240	Thompson	
MGL15101636	035	2015-06-15	00:08	39	39.19423	-73	41.22577	2015-06-15	06:25	39	22.50098	-73	10.90118	5130	1	865	4266	67-68	0.5	4.096	240	Thompson	
MGL15102524	036	2015-06-15	07:32	39	24.92452	-73	38.60297	2015-06-15	14:02	39	41.60155	-73	38.86039	860	1	5137	4278	69-70	0.5	4.096	240	Thompson	
MGL15101612	037	2015-06-15	15:10	39	39.18080	-73	41.37743	2015-06-15	22:08	39	22.44292	-73	10.95482	5142	1	865	4276	71-72	0.5	4.096	240	Thompson	
MGL15102690	038	2015-06-15	23:16	39	24.90197	-73	38.76303	2015-06-16	06:25	39	41.66597	-73	39.09662	872	1	5137	4293	73-74	0.5	4.096	240	Thompson	
MGL15101598	039	2015-06-16	07:33	39	38.11442	-73	41.40737	2015-06-16	14:08	39	23.37757	-73	11.01937	5147	1	865	4283	75-76	0.5	4.096	240	Thompson	
MGL15102476	040	2015-06-16	15:57	39	24.76313	-73	38.74110	2015-06-16	22:13	39	41.54130	-73	39.15388	858	1	5137	4279	77-78	0.5	4.096	240	Thompson	
MGL15101564	041	2015-06-16	23:23	39	38.89080	-73	42.20367	2015-06-17	05:32	39	22.36607	-73	11.08085	5102	2	864	4240	79-80	0.5	4.096	240	Thompson	
MGL15102452	042	2015-06-17	06:40	39	24.69280	-73	38.78512	2015-06-17	13:01	39	41.47038	-73	39.21782	857	1	5137	4281	81-82	0.5	4.096	240	Thompson	
MGL15101540	043	2015-06-17	14:09	39	38.98210	-73	41.52675	2015-06-17	20:31	39	22.23458	-73	11.46852	5140	1	865	4275	83-84	0.5	4.096	240	Thompson	
MGL15102428	044	2015-06-17	21:41	39	24.67550	-73	39.90743	2015-06-18	04:06	39	41.40457	-73	39.27905	866	4	5137	4275	85-86	0.5	4.096	240	Thompson	SOL-2412 NTBP d/t gun problem
MGL15101516	045	2015-06-19	05:24	39	38.94060	-73	41.64013	2015-06-18	12:10	39	22.17488	-73	11.20132	5147	1	865	4282	87-88	0.5	4.096	240	Thompson	
MGL15102404	046	2015-06-18	13:16	39	24.56883	-73	38.92296	2015-06-18	20:09	39	41.34103	-73	39.33725	856	1	5137	4280	89-90	0.5	4.096	240	Thompson	
MGL15101756I	047	2015-06-18	22:01	39	38.67728	-73	40.84682	2015-06-18	22:31	39	38.42810	-73	38.71550	5136	1	4830	306	91	0.5	4.096	240	Thompson	Line terminated d/t P-Cable failure
MGL15101756J	048	2015-06-19	04:06	39	25.72462	-73	16.37710	2015-06-19	05:15	39	22.62600	-73	10.78720	1651	1	865	790	92	0.5	4.096	240	Thompson	
MGL15102572S	049	2015-06-19	06:24	39	25.05140	-73	38.49663	2015-06-19	10:45	39	35.99832	-73	28.86020	860	1	3701	2842	93-94	0.5	4.096	240	Thompson	
MGL15101900I	050	2015-06-19	12:51	39	35.08160	-73	31.68717	2015-06-19	17:19	39	22.56487	-73	10.84252	3865	1	3020	864	95-96	0.5	4.096	240	Thompson	
MGL15102380	051																						